


DIGITAL PANEL METER MODEL AP-241A Series INSTRUCTION MANUAL



Caution

- (1) The application of voltage or current exceeding its maximum allowable value to the input terminals may result in instrument damage.
- (2) The supply of power out of its allowable range may cause fire, electric shock or instrument failure.
- (3) The content of this manual may subject to change without prior notice for product improvement.
- (4) The manual is carefully prepared. However, if any question arises, or any mistake, omission or suggestion is found in the content of this manual, contact your nearest our sales agent.
- (5) After read this manual, please keep it as anytime can see.

1. Outline

The Model AP-241A Series digital panel meter is an extremely small 4 1/2-digit meter used only for display, and satisfies the DIN size.


As its power supply voltage, both 5V DC and 24V DC are available. For both, input terminals are isolated from power supply terminals. And one measuring range code can be selected from among three measuring range codes depending on the measuring range. For A/D conversion, this meter employs the double integral method and has various functions such as differential input (for the range code of "12") holding, etc.

2. Specifications

Model and Range codes	Measured range	Max. resolution	Input impedance	Max. allowable Input Voltage
AP-241A-12	$\pm 1.9999V$	100 μV	100M Ω	$\pm 100V$
AP-241A-13	$\pm 19.999V$	1mV	1M Ω	$\pm 250V$
AP-241A-14	$\pm 199.99V$	10mV	10M Ω	$\pm 500V$

Accuracy: $\pm (0.03\% \text{ of rdg} + 1 \text{ digit})$ ($23^\circ C \pm 5^\circ C$ 35 to 85% RH)

Model NO. Configuration




3. Common Specifications

Measurement function	: Specify one Model from among 3 DC voltage measurement models.
Operation method	: Double integral
Input type	: Differential input (For the "12" range code) Single-ended type (For the "13" and "14" range codes)
In-phase voltage	: MAX $\pm 1V$ (For the "12" range code)
Input bias current	: 100pA (TYP.)
Sampling speed	: 2.5 times/sec.
Noise rejection ratio	: NMR 50dB (TYP) (50/60Hz)
Maximum display	: 19999
Overrange warning	: "0000" flashes for input signal exceeding the maximum display.
Display	: Red LED numeric elements character height -8mm
Polarity	: Automatic polarity selection.
Polarity display	: " - " is automatically displayed for negative input signal.
External control	: External hold: Negative signal of 0V or contact signal. (short) External start: Positive pulse from 0V to +5V for more than 1ms or contact signal. (open)
Decimal point	: Settable to any position.
Operating temperature/humidity range	: 0 to 50°C 35 to 85%RH (No dew-condensing)
Power supply	: 5V DC $\pm 5\%$
Power consumption	: 65mA (TYP.)
Dimensions	: 48mm (W) $\times$ 24mm (H) $\times$ 73mm (D)
Weight	: Approx. 55g
Dielectric strength	: Between input terminal (LO) and mounting panel, For 1 min. at 1500V AC
Data output	: BCD multiplex
Accessories	: Instruction manual 1 copy

4. Operation


4-1 Mounting

- 1) Mounting the meter on panel
Make the panel cutout as shown in Fig. 1, then insert the meter into the panel through the panel cutout as shown in Fig. 2. (Recommended panel thickness: 0.8 to 3.5mm)
- 2) Removing the meter from the panel surface
Hold the hooks shown in Fig. 2 with the thumb and middle finger, then push them in the mainframe. Push the mainframe out of the panel cutout from the back toward the panel front.



3) Removing the internal circuit board from the case

Lightly rotate a screwdriver inserted in the hole at the bottom of the mainframe to remove the front meter panel from the case. Next, disconnect the connector, then expand the case front in the up and down direction with the screwdriver inserted in the gap between the LED display and case as shown in Fig. 3 to disengage the hook from the internal circuit board. Thus, the internal circuit board can be pulled out of the case by pushing it from the back toward the front.



4-2 Connecting connector

Connect the attached input/output connector to the rear of the panel meter.

As this connector touches on one side, do not turn upside down.

1) Connecting the power supply

Connect the power between the No. 9 (0V) and No. 10 (+5V) terminals of the connector. Use a power supply voltage of 5V DC $\pm 5\%$. (As this meter is not provided with a power switch, it is ready to operate when the power is connected.) This meter has not a built-in fuse.

If a fuse is required for safety, externally connect the fuse with a rating current of 0.2A.

2) The position of the decimal point can be freely set by shorting the following terminals of the connector. The decimal point is not set to any position prior to factory shipment. Therefore, set the position of the decimal point as desired at the site.

Decimal point to be lit	Connector terminal No. to be shorted
10 ¹ decimal point	5-3
10 ² decimal point	6-3
10 ³ decimal point	7-3
10 ⁴ decimal point	8-3


3) Connecting the input

For the signal-ended input type, connect the input signal between HI (1) and LO (2) for each range, and also connect the LO terminal to the analog ground terminal (3) at one point on the signal source side.

In order to lessen the effect of noise, use a 2-core shielded cable, and connect the LO terminal to the analog ground terminal, then connect the shielding wire to the analog ground terminal. The DC voltage range (range code: "12") can also be used for differential input. In this case, connect input signal E1 between the HI (1) and analog ground (3) terminals and also E2, between the LO (2) and analog ground (3) terminals to measure differential input voltage $E1-E2=Ei$. For input signal connection, use a 2-core shielded cable and connect the shielding wire to the analog ground terminal. Use the LO terminal at in-phase voltage between -1V and +1V with respect to the analog ground.

Never apply any voltage exceeding the maximum allowable voltage between the input (HI or LO) and analog ground terminals.

Connector diagram



4) Start/hold

The displayed value can be held by shorting the HOLD terminal with the COM terminal, or by setting the HOLD terminal to level "0".

Measurement also starts by opening these terminals or by setting the HOLD terminal to level "1" at the necessary timing. The minimum time required for one measurement [positive pulse from 0V to +5V for more than 1ms or contact signal (open)] is approx. 400ms.

As the input (LO) and 0V power (No. 9 terminals) of this meter are connected each other, and thus they are not DC-separated and isolated, perform control as much as possible by using Mechanical contact signal such as relay, switch, etc. When performing control by using TTL or transistor, externally add such a circuit as shown in Fig. 4. (For floating input, this circuit is always required for isolation.)

