16. WPMZ-6 Monitor at Ethernet, converting Modbus RTU to TCP

Point

1) Measured data by WMB & WPMZ, and convert RS-485 Modbus RTU to Ethernet Modbus TCP by Modbus TCP/RTU converter.
Then you can monitor data at PC on Ethernet.

2) Our WMB & WPMZ are Modbus RTU slave units.