6. WPMZ-3 Weight measurement by Load cell





Loadcell signal
-3.5mV/V~3.5mV/V

Alarm output
Relay /
Opencollector
(4 setpoints)

Option output
RS-232C / RS-485 /
BCD / Analog output



Load cell
For 3 ton or more
Rated output : -3.5mV/V~3.5mV/V

Load cell meter
WPMZ-3-□-SX-□□-XE0
Input : -3.5mV/V~3.5mV/V
Relay output : 4 set point (AL1/AL2/AL3/AL4)
Option output : Analog/RS-232C/
RS-485/BCD
Power supply : Please inform