




14. WPMZ-5 2ch input, Conveyor rotation / speed

WPMZ-5 Application : Conveyor

Rotation and Speed measurement of conveyor by WPMZ-5

Example



2 input Calculation	Calculation method
Absolute ratio	$(B/A) \times 100$
Relative error	$(B/A-1) \times 100$
Subtraction	$B-A$
Density	$(B/(A+B)) \times 100$
Sum	$A+B$