

7. WPMZ-3 Surface measurement by Lasor sensor

Measure surface of roof tile by Lasor sensor, and OK/NG judgement by compare result.



Wave compare display (OK/NG judgement)

- 1) Create Comparison waveform.
- 2) Start measuring at Trigger ON by external control function.
- 3) Measure and compare with comparison waveform.
- 4) Alarm output by relay when NG.
(NG when measurement waveform is over comparison waveform)

(Display example)

