


8. WPMZ-3 Weight measurement of Conveyor

Conveyor at Site



Weight measurement of Conveyor at Site

Load cell



x2ch
Load cell
input




Strain gauge meter WPMZ-3

- 2ch Load cell signal input
- 2ch calculation function
- LCD Display
- Waveform comparison
- Multi hold function
- Alarm output (Relay / Open collector)
- Option output (BCD / Analog / RS-232C / RS-485)

Alarm output


Relay / Opencollector
(4 setpoints)



Alarm lamp /
Signal tower /
Buzzer /
etc.

Option output

RS-232C / RS-485 /
BCD / Analog output



Computer

PLC
Etc.

Waveform comparison

