
1. Assembly procedure

Assembly the product by referring to the following diagram. Finally, insert the acrylic cover firmly in the front holder.

2. Parts names

Only parts Nos. (1), (3) and (4) are included in this product.

No.	Name	Q'ty
1	Acrylic cover	1
2	Set (Mainframe)	
3	Rubber packing	2
(4)	Front holder	1
5	Panel cutout	
6	Set mounting bracket	
7	Setscrew	



watanabe

WATANABE ELECTRIC INDUSTRY CO., LTD.

6-16-19, Jingumae, Shibuya-ku, Tokyo 150-0001, Japan Phone: (81)3-3400-6141 Homepage http://www.watanabe-electric.co.jp/en/